MAIWO

User Manual

KC015 PCIe Card

Product name：

MAIWO KC015 PCIe X1 to 3-port USB HUB+1000M network port expansion card


- USB HUBX3
- 1000M Network
- 15Pin SATA power supply port
- PCIe X1

Item name:	PCIe X1 to 3-port USB HUB+1000M network port expansion card
Support:	3xUSB HUB 1000M network
Interface:	PCIe X1 is compatible with x4/x8/ X16 card slots
Connector:	Usb3.0-5gbps transmission bandwidth
Materials:	Metal base + glass fiber plate
power supplys:	PCIe interface +15Pin SATA dual power supply interface
Size:	112(L)*120(W)*18.6(H) MM
System:	Windows7/8/10/Linux

―――① ―――

Installation

1 . Insert express card to PCIe×1/4/8/16 slot on motherboard;

2 . Fix full profile bracket with tower panel of PC.

PCIex1/4/8/16

―――② ―――

Installation

3. The network indicator light:green illuminate when power connected and flash yellow when transfer data

4.15pin SATA power cable ,ready for PCIe power is weak

Green light
Yellow light

―――③ ―――

Note: Initialize the partitioned hard disk step when the USB interface is connected to the new removable hard disk

Ⅰ. New hard disk format:

1. View "computer-Manage-disk management" to Find the New disk.


―――④ ―――

Ⅱ. New hard disk format:

2. Right click the "External disk",then click "New simple Volume".



―――⑤ ―――

Ⅲ. Hard disk partition:

3. According to the instruction, choose the size of partition,then dick "Next" to finish.

―――⑥ ―――

Ⅳ、Hard disk partition:

4. Then you can find the new hard disk in the "Computer", it's ready to be use.

initialization, partition and format

1.1 View "computer - Manage - disk management" to Find the new disk .

Remark: There two types MBR and GPT. SSD capacity <=2T, please choose MBR, if more than 2T, choose GPT.

2.2 Right click the "Disk 1", then click "New Simple Volume".

―――⑦ ―――