# RW-H43 BLUETOOTH HEADSET
INSTRUCTION MANUAL

Bluetooth LED

- LED Off: Bluetooth Off
- Green LED on: Bluetooth power on and no device is connected.
- Green LED blinking slowly: Device is Connected
- Green LED blinking fast: Pairing Mode
- LED is off: Charge complete
- Red LED blinking slowly: Battery in charge

Bluetooth Multi Function Button (MFB)

- Long press (4 ~ 6 seconds): Turn on the Bluetooth
- Short press: Answer call, hang up call, play music, or pause music
- Long press while Bluetooth is on (2 seconds): Turn off the Bluetooth

How to Pair

1. Make sure the Bluetooth is off (no LED light)
2. Press the Multi Function Button (MFB) for 8 seconds until the Green LED is blinking fast.
3. Go to your bluetooth device (cellphone, smart phone, IPOD, or computer).
4. Search for a device name "Rugged"
5. Pair and connect the device.

Headset Functions Diagram

LED (Green/Red)

Multi Function Button (MFB)

Charging Port

Electrical Specifications

RF Type	Bluetooth 2.1+EDR Class 2
Frequency	2.400 - 2.485 GHz
Max Transmit	+4 dBm
RF Sensitivity	-80 dBm
Battery	3.7v Li-Ion 600mAh (1500 mAh for extended battery)
Charging Voltage	5Vdc Only
Operation Life	At least 24 hours with continuous talking or listening
Standby	More than 10 Days
Charging Time	3 - 10 Hours