Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.

Order No 2818

EZ Soldering Coupler for Dean's Ultra Plugs

1. Solder wire (up to 12 GA) into solder cup
2. Place heat shrink over the wire(s) & push the split tip onto Dean's Ultra Plug
3. **SOLDER** the connection to the Dean's Ultra plug & shrink.