Product Release Notes

Scan Tools and Code Readers

Release Date:	June 2023
Software Version:	V1.88.02
Firmware Version:	v22.01.05

Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on how to perform a software / firmware update on your diagnostic scan tool or code reader.

Affected Product(s)

- INNOVA® 7111 Smart Diagnostic System

New / Added Features & Functions

- Add 30 min option to Idle Time settings

Fixes / Updates

- Support operation hours update
- UI Logic issues
- Missing LD PIDs
- Email report header update
- Inconsistent parts pricing display
- Improve WiFi password entry time
- Improve Live Data initial response time
- Other minor bug fixes and tool enhancements.

Product Support

Please visit us at innova.com/support for additional information.