Step-by-Step Directions

1. Create sublimation design for desired blank.
2. If using a cutting machine, refer to the Artesprix Heat Resistant Transfer Mask Cutting Directions. If "fussy cutting," cut mask using scissors. Do not remove clear film before cutting.
3. Remove clear film from back of cut design.
4. Place cut design on blank, adhesive side down as desired.
5. Apply finished sublimation design to blank with adhered resistant mask shape using heat tape.
6. Transfer according to the sublimation specifications of the blank.
7. Carefully reveal design after transfer.

Things to Remember:

- Where the mask was placed on the sublimation blank, the finished design will be the original color of the blank.
- Sublimation Blanks that are non-completely flat surface may allow ink to seep through which will achieve a muted look where the mask was placed.
- If you are using the mask to add text, your adhered mask should not be mirrored.
- Electric die cutting machines are also a great tool for cutting desired shapes.

122123A

- **For use with Sublimation Designs to create resistant effect**
- **Cut to desire shape and place on sublimation blank before transferring sublimation design**
- **Can withstand temperatures up to 400° F**

Cutting Directions

Cricut Explore 3

1. Open Design Space
2. Click '+ New' to start a new project
3. Search for desired design under 'images' or hit 'TEXT' to type a phrase or word
4. Select 'Make It' to send to cut
5. Place Heat Resistant Transfer Mask on Cricut Mat, Green side up
6. Select 'Continue'
7. Choose 'Premium Vinyl Setting'
8. Press the Flashing Arrow Button on your Cricut Explore 3 machine to load the mat
9. Select the ▶ or 'Cut Button' on your Cricut Explore 3 machine
10. Once the design is cut, press the Arrow Button on Cricut Explore 3 machine for the mat to unload
11. Peel back clear backing to use Heat Resistant Transfer Mask for your sublimation project

Silhouette Cameo 3

1. Open Silhouette Studio
2. Select 'Library' from the tool bar
3. Search and select your desired design
4. Select 'Send' from the tool bar (this will open the 'Send Panel')
5. Choose 'Vinyl Glossy'
6. Place Heat Resistant Transfer Mask on Silhouette Mat Green side up
7. Press 'Load' from the control panel on the front of the machine. The Silhouette Cameo will automatically pull the mat if it is loaded properly.
8. From in the Send Window, select 'Send'
9. Once the Heat Resistant Transfer Mask is cut unload the mat from the machine
10. Peel back clear backing to use Heat Resistant Transfer Mask for your sublimation project

Brother Scan N Cut

1. Turn on Brother Scan N Cut
2. Place Heat Resistant Transfer Mask on low tack mat
3. Open the Brother Canvas for PC Program
4. Insert desired shape or text
5. Select 'File' in the top left hand corner
6. Scroll down the select 'Transfer FCM File VIA the Internet'
7. When window opens confirming the transfer, select 'OK'
8. Select 'Press and Retrieve Data Button' on the Scan N Cut
9. Press the computer with wifi symbol
10. Press the mat button to load the mat
11. Select 'Cut' then select the wrench icon
12. Scroll down and select 'Half Cut', then select 'ON'
13. Select 'OK', then 'START'
14. Once the Scan N Cut has completed the cutting process, press the mat button to unload the mat
15. Peel back clear backing to use Heat Resistant Transfer Mask for your sublimation project