

Required tools



Hardware included



6x
Screws

2x (+1 extra)
Studs

6x
Chicago bolts

6x
Washers + spring washers

6x
Plugs

1x
Allen key

Components included



3x
Rise

4x
Climb

2x
Chill

1x
Mount + Caps

6x
Connector

2x
Scratch



2x
Chill basket

2x
Climb cover

01

Indicate where to drill



02

Drill holes and fix the bottom Mount









03

Connect the Rises



04

Connect the Rise to the bottom Mount with the Cap





05

Connect the top Mount to the Rise with the Cap



06

Indicate where to drill



07

Take off the Rise, top Mount and Cap from the bottom Mount



08

Drill holes and install the top Mount









09

Connect platforms to the Connectors

E CLIMB x4	G CHILL x2





10

Slide over the Rise





11

Install the Rise with platforms between the Mount



12

Add Scratch over the Rise



13

Add Climb cover and Chill basket to the platforms



Finished