Skylight joint

- Cut vapour control layer

- Cut vapour control layer to reveal depth

- Affix Corvum to vapour control layer with the folded edge flush with the sheet edge
- Press on

- With the backing strip folded back insert Corvum accurately into the groove, **affix Corvum all the way to the corner**
- Successively remove backing strip
- Press on

5

- Mount the remaining vapour control layer sheets: Cut sheet to size
- Affix Corvum with the folded edge flush with the sheet edge on three sides

6

- With the backing strip folded back insert Corvum accurately into the groove
- **Affix Corvum all the way to the corner**
- Successively remove backing strip
- Press on

7

- Seal the sides

8

- Cut out 90° angle pieces from 4 short pieces of Corvum
- Seal the corners

9

• Finally seal the overlaps using Sicrall 60

10

How it should look:

• Skylight permanently airtightly sealed with Corvum 30/30 and Sicrall 60

Corvum® 30/30   P. 116