MIELE MANUFACTURING

How to Unpartition a Hard Drive

1. Go to the windows desktop by singing in and going to "System" then "Terminate" and close out of "Run Shortcut".


2. Unplug one of the USBs on the back of the computer and plug in a keyboard, select the Windows icon and type in the search bar "Create and Format" then select the "Create and Format Hard Disk Partitions".

3. Once opened, select and hold on the "D:" drive to bring up the menu and select "Delete Volume".


4. Select "Yes".

5. Select and hold on the "C;" drive to open the menu and select "Extend Volume".

6. Select "Next".

7. Select "Next."

8. Select "Finish".