BLACKMAN CRUZ
WORKSHOP *LOS ANGELES*

CARE INSTRUCTIONS

THANK YOU FOR YOUR RECENT PURCHASE FROM OUR BC WORKSHOP COLLECTION. THE ENTIRE BC WORKSHOP SERIES IS DESIGNED AND MANUFACTURED IN LIMITED QUANTITIES IN LOS ANGELES BY LOCAL ARTISANS. EACH PIECE IN OUR COLLECTION IS INDIVIDUALLY CRAFTED. AS A RESULT, SLIGHT VARIATIONS IN PATINA, FINISH AND GRAIN MAY OCCUR.

CALIPER PENDANT, SMALL

POLISHED BRASS WITH FROSTED GLOBE
48" DROP X 10" DIAMETER

CLEANING INSTRUCTIONS FOR POLISHED BRASS

BRASS PRODUCTS ARE SENSITIVE TO MOISTURE AND DIRECT HEAT. AVOID PLACING PRODUCT IN DIRECT CONTACT WITH HEATING VENTS, INTENSE DIRECT SUNLIGHT OR AREAS EXPOSED TO MOISTURE OR DENSE HUMIDITY. NON-LACQUERED BRASS WILL EVOLVE OVER TIME. PATINA WILL VARY, APPEARING LIGHTER OR DARKER IN AREAS. FINGERPRINTS WILL APPEAR WHENEVER ITEM IS TOUCHED. USE A MICROFIBER CLOTH OR SOFT, CLEAN RAG TO CLEAN ITEM. DO NOT USE ANY TYPE OF WATER WHEN CLEANING AS WATER CAN TARNISH BRASS AS THERE IS NO LACQUER OR PROTECTIVE COATING. TO BRIGHTEN YOUR PIECE, WE SUGGEST NEVER DULL. WE RECOMMEND THIS CLEANING 1 – 2 TIMES A YEAR. AVOID USING HIGHLY ABRASIVE SCRUBBING MATERIALS, METAL BRISTLED BRUSHES, STEEL WOOL OR BLEACH-BASED CLEANERS. MATERIALS SUCH AS THESE WILL SCRATCH THE SURFACE OF THE BRASS.

CLEANING INSTRUCTIONS FOR FROSTED GLOBE

TO CLEAN THE FROSTED GLOBE, USE AN EVERYDAY CLEANING PRODUCT SUCH AS WINDEX TO WIPE FREE ANY DUST OR BUILD-UP. AVOID USING ANY CLEANING PRODUCTS THAT CONTAIN HARSH SCRUBBING AGENTS OR BLEACH AS THESE AGENTS WILL SCRATCH THE SURFACE OF THE GLOBE.

ALL PRODUCTS ARE CONSIDERED TO BE IN GOOD CONDITION AND ERROR-FREE WHEN DELIVERED. CLIENT SHOULD INSPECT ALL DELIVERIES IMMEDIATELY UPON ARRIVAL, AND SHOULD MAKE NOTE OF ANY DAMAGE WHEN SIGNING FOR THE PRODUCT DELIVERY.

ALL BC WORKSHOP PRODUCTS CARRY A ONE-YEAR WARRANTY. IF CLIENT FINDS A MATERIAL DEFECT IN ANY PRODUCT, PART OR COMPONENT WITHIN ONE (1) YEAR OF PURCHASE, PLEASE CONTACT BLACKMAN CRUZ. BLACKMAN CRUZ WILL NEED TO DETERMINE IF CARE, MAINTENANCE, INSTALLATION AND OTHER FACTORS CONTRIBUTED TO PRODUCT DEFECT.