AZ-Delivery CNC Shield V3
Pinout



Table 1. Microstepping Resolution Truth Table

MS1	MS2	MS3	Microstep Resolution
			Full Step
J			Half Step
	J		Quarter Step
J	J		Eighth Step
J	J	J	Sixteenth Step

J= jumper