

## WARRANTY - WHAT IS INCLUDED AND WHAT IS NOT

**Special Note:** If the ball shows a "red" color in the valve needle opening, it was manufactured prior to 2009, and there is no longer any warranty.



Red Valve Insert  
**NO Warranty**

The following pictures show what is covered under manufacturing defects



Spacer Alignment Error  
**Warranty**



Cross Cut (possible spacer separation) **Warranty**



Valve Separation  
**Warranty**

**Pinches, punctures and other failures caused by bad installation, wrong air pressure, etc., are not covered under the manufacturing defect policy.**



Rim Pinch  
**NO Warranty**



Ball Puncture  
**NO Warranty**