

HONDA VTX1300S

Parts list for MCS 4620

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCSU 400C	Computer
2	5	8cm lengths	Foam mounting tape
		<u>MCS 1632</u>	<u>Vacuum actuator assembly</u>
3	1	MCS 574	Vacuum actuator
4	1	MCS 1632A	Actuator mount bracket
	3		6 gauge x 1/2" pan head self tap screw
	1		6 gauge x 3/8" pan head self tap screw
5	1	MCS 574D BS	Solenoid housing dust cover
	1	MCS 574F	Rubber grommet 3/8" x 1/2"
6	1	MCS 574E BS	Diaphragm housing dust cover
		<u>MCS 1637</u>	<u>Vacuum hose assembly</u>
7	1	MCS 032	Vacuum stop valve
8	1	MCS 031	4mm Vacuum Tee connector 4mm Vacuum hose
		<u>MCS 4624</u>	<u>Switch assembly</u>
9	1	MCS 820	Switch
10	1	MCS 830C	Switch bracket
	4		4 gauge x 1/2" pan head self tap screw
11	1	MCS 4621	Wiring loom
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor terminal (yellow wire)
d			Speed sensor connectors (co-axial wire)
e			Actuator plug (4 pin)
f			Power & brake sensor (orange and grey wires)
g			Ground connector (black wire)
h			Clutch sensor (blue wire)
i			Control switch plug (6 pin)
12		<u>MCS 4625</u>	<u>Cable Interface Unit (CIU) assembly</u>
13	1	MCS 4625A	CIU housing
14	1	MCS 003F	Actuator spool
15	1	MCS 4626	Dual spool
16	1	MCS 003H	Bush
17	1	MCS 003K	End Cap
18	1	MCS 1635B	CIU mounting bracket
19	1		M5 x 45 bolt
20	2		5mm flat washer
21	1		M5 Nyloc nut
22	1		M4 x 10 pan head screw (actuator cable retainer)
23	1	MCS 500	Carburettor cable
	10		100mm cable ties
	10		150mm cable ties
	5		200mm cable ties

Information, Set up and Operation Manual
Operation and User Manual
Installation Manual
Trouble shooting guide

