




Copper tubing touching



① Unscrew all 6 screws



② Lift off top.



③ Above shows copper tubes touching.



④ Gently bend tubes apart.




⑤ Above shows copper tubes touching compressor.



⑥ Gently bend tubes away from compressor.



⑦ Put back top.



⑧ Screw in all 6 screws.