




E I C H H O L T Z

110002 CABINET CIPRIANI

ASSEMBLY INSTRUCTION

PARTS

3x




(A)

1x



(B)

12x



(C)

12x



(D)

4x




(E)

1x



(F)

2x



(G)

4x




(H)

20x




(I)

5x



(J)

1



2

