


Traditional Brown Patinas for Bronze, Brass, and Copper




Honeycomb on Bronze



Ferric Nitrate Ferric Chloride
Hot on Brass



Liver of Sulfur Hot on Copper




Copper Sulfate on Brass




Copper Rust on Copper



Rustic Brown on Copper



Darkening on Copper



Deep Brown on Copper



Antiquing on Copper