


PLEASE READ INSTRUCTIONS THOROUGHLY TO ENSURE PROPER INSTALLATION. IF YOU ARE UNCONFIDENT IN YOUR ABILITY TO PERFORM ANY OF THE TASKS SAFELY, PLEASE SEEK THE SERVICES OF A PROFESSIONAL.

# A90/J29 SUPRA EXTINGUISHER MOUNT



## INCLUDED PARTS + REQUIRED TOOLING

- A. 3/16" ALLEN SOCKET OR KEY
- B. 1/8" ALLEN SOCKET OR KEY
- C. T50 TORX SOCKET
- [ 1X RATCHET ]

- A. RSPRO MOUNT BRACKET
- B. HARDWARE BAG: [ 4 SMALL 1/8"MM ALLENS + LARGE WASHERS ]

- A. RENNLIN BASE
- B. FIRE EXTINGUISHER
- C. RENNLIN CLAMP [ 2 ALLEN BOLTS ]

## SUB-ASSEMBLY



PLEASE FOLLOW THE ASSEMBLY INSTRUCTIONS PROVIDED BY RENNLIN TO SECURE YOUR BOTTLE WITHIN THEIR CLAMP.



## STEP 1

COMPONENTS 1C + 2A + 2B

TOOLING 1/8" Allen



OPEN THE SMALL HARDWARE BAG [COMPONENT 2B] AND REMOVE FOUR 1/8" ALLEN BOLTS. ALIGN THE RENNLIN BASE PLATE WITH THE HOLES ON THE TOP OF THE RENNSCOT MOUNTING BRACKET [OPEN SIDE FACING FORWARD] AND TIGHTEN IT IN PLACE WITH THE AFOREMENTIONED HARDWARE.



# RESULTS SUB + 1



COMPONENTS  
1 A + 1B 1C +  
2A + 2B

MOVE TO THE INTERIOR OF THE  
VEHICLE




# STEP 2



TOOLING  
T50 TORX +  
RATCHET



LOOSEN AND REMOVE THE TWO FRONT  
SEAT RAIL BOLTS. THEY ARE T50 AND  
TORQUED FAIRLY TIGHT.



# STEP 4



COMPONENT  
2B [large  
washers from  
hardware bag].



PLACE THE PROVIDED WASHERS IN THE  
TOP RECESS OF THE SEAT RAIL (ONE  
PER SIDE) BEFORE PLACING THE  
EXTINGUISHER BRACKET ON TOP.

# STEP 4



TOOLING  
T50 TORX +  
RATCHET



PLACE THE EXTINGUISHER BRACKET  
OVER THE WASHERS, AND REPLACE THE  
T50 TORX SEAT RAIL BOLTS. TORQUE  
TO SPEC.



FIRMLY  
PRESS IN  
RENNLINE  
CLAMP.

THANK YOU FOR CHOOSING RENNSCOT.



## WARRANTY & DISCLAIMER

Rennscot, LLC (the "Company") will warranty all products manufactured by Rennscot, LLC against any and all manufacturer's defects in materials and workmanship which affect the reasonable operation of the product for a period of one month from receipt. This warranty is non-transferable. Warranty claims must be made by contacting the Customer Service Department by emailing [sales@rennscot.com](mailto:sales@rennscot.com)

Rennscot, LLC will repair or replace only those products determined to be defective by the factory in the Company's sole discretion. This warranty does not apply to normal wear and tear of the product or protective finishes.

### Warranty Conditions

1. The Buyer is required to inspect the goods immediately upon receipt from the Company. Subsequent claims related to obvious defects will not be accepted by Rennscot, LLC

2. For any claims on the Product, if purchased through an authorized Rennscot dealer, the Buyer must submit the claim within the proscribed time frame herein to the dealer from whom goods were purchased.

3. The right to make a claim under this warranty given by the Company expires upon any of the following: a. Failure to present the original proof of purchase; b. Failure to have the product installed by a licensed auto mechanic with the experience and knowledge of the Product; c. Failure to follow any provided installation instructions (if any); d. Damage to the Product during transportation (such damage must be claimed directly with the shipping company); e. The need to replace or repair the Product arose from the malfunction of another car part not covered by this Warranty; or f. The Claim is related to or from an accident involving your vehicle. Rennscot, LLC., expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose or application, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of any products or services. The Company assumes no responsibility or liability for damages resulting from the installation of the Product. Any liability for consequential and/or incidental damages is expressly disclaimed. The Company's liability in all events is limited to, and shall not exceed the purchase price paid. Rennscot, LLC., disclaims any liability for product defect claims that are due to product misuse, improper product selection or misapplication.