

Kit Inventory Contents

RF157016-26A (GM)		
Replaces PCM 40I Inline 1:1 ratio P.N. RA157016 on GM Engines * Also replaces 40I 1:1 ratio transmission used with the Walter V-drive (RV26-D)		
Kit Part No.	Description	Part No.
RF157016-26A	80I Transmission	RA157026
	Model: 30-03-M01	
	Ball joint	R178003
	Bolt	98446030 (6)
	Bolt	RS0337 (4)
	Cooler - 12"x1 1/4"	R147006
	Damper	R140023
	Damper bolt	R009092 (6)
	Elbow	R024010 (4)
	Flat washer	92300000 (6)
	Hose	RA045007B
	Hose	RA045007H
	Lockwasher	RS2180 (6)
	Lockwasher	RS2181 (4)
	Nut	97440000
	Nut	RS1568
	Shift bracket	R090407
	Washer	93940000 (6)
	Shift bracket	R090408
	Retainer	R090086
	Screw	91014063 (2)
	Nut	95014300 (2)