

Twin Diesel Volvo Penta TAMD71b & Kohler Genset in 57' Navigator

From: Dahlin, Timothy L [<mailto:timothy.l.dahlin@boeing.com>]

Sent: Thursday, January 08, 2009 3:44 PM

To: Nancy Dixon

Subject: RE: Cerma

They smoke when cold as usual. But they appear to smoke a little less as they warm up. The one thing I have noticed for sure is that there was some definite fuel residue being dumped into the water from the starboard engine exhaust. That has now gone away.

Tim

Building 17 Office 6B14

Office (714) 896 - 2651

Cell (714) 625 - 2414

Fax (714) 372 - 1887

