

FULL SWEEP PRESSURE WITH 1/8" NPT SENDER HARNESS WIRE IDENTIFICATION AND POSITION



(viewed from the wire IN side of the plug)

WIRING DIAGRAM (viewed from the wire IN side of the plug) 1. Purple - Signal from sensor to gauge 2. Gray - 5 volt reference power 3. X=Empty 4. White - Dash lights, or may be empty for non LED gauges. 5. X=Empty 6. Red - 12 volt switched power 7. Black - Ground to sender 5227 8. Black - Gauge ground **Harness** 9. X=Empty 10. X=Empty (viewed from the wire IN side of the plug) **10** 9 8 **EMPTY EMPTY** 5 2 **EMPTY EMPTY**