



INTERPRETATION GUIDE

Cross-Check P - CI 115


UNEXPOSED



CORRECT COLOR CHANGE



INSUFFICIENT



74 Inverness Drive East - Englewood, Colorado 80112

Phone: 303-660-4201 - Fax: 303-660-4213 - E-mail: info@steritecproducts.com -

Website: www.steritecproducts.com

MK-066 Rev. A