


# INTERPRETATION GUIDE

## Cross-Check F - CI 118


### UNEXPOSED



### CORRECT COLOR CHANGE



### INSUFFICIENT



74 Inverness Drive East - Englewood, Colorado 80112

Phone: 303-660-4201 - Fax: 303-660-4213 - E-mail: [info@steritecproducts.com](mailto:info@steritecproducts.com) -  
Website: [www.steritecproducts.com](http://www.steritecproducts.com)

MK-065 Rev. B