# **Dry-Checks Dry Heat Indicator Strip**CI 136

The Dry-Checks Dry Heat Indicator Strips are designed for use in dry heat sterilizers at 160°C. The indicator provides clear identification of processed and unprocessed items. When used as directed, Dry-Checks give visible confirmation that the sterilized item was exposed to dry heat.



# **Key Features**

- For use in dry heat sterilizers operating at 160°C
- Color change in 7 minutes

### **Performance Characteristics**

When exposed to dry heat conditions, the indicator check mark changes color.

# **Physical Characteristics**

Dimensions: L 97mm x W 19mm

### **Color Change**

Green to black

### **Complete Color Change Time**

7 minutes at 160°C

## **Storage**

The storage conditions are printed on the product packaging. Store in the resealable bag provided

### **Shelf Life**

36 months from date of manufacture. The expiry date is printed on the product packaging

### Standards Classification

ISO 11140-1, Type 4

SteriTec Part No.	<b>Packaging</b>
CI 136, Dry Checks Dry Heat Indicators	20 boxes of 250

