




Blue AGAVE TORCH MANUAL

- 1 Stack leaves onto the base plate starting with #1. Make sure locator tab slides through slot in leaf.
Note: Flare open first few leaves.

- 2 After leaf #11 place the washer on the bolt as shown.

- 3 Screw flower stem to bolt on base.

- 4 Mount or stake down fully assembled piece using holes in the base plate.



FILLING

Use citronella torch fuel or other suitable torch fuel, such as lamp oil (not for use with propane). Unscrew flame guard & wick. Keep torch wick inserted in metal flame guard while filling.
NEVER USE GASOLINE, ALCOHOL OR SOLVENTS.

LIGHTING

Allow wick to become completely saturated before lighting. To extend run time, check fuel level frequently to ensure wick stays saturated while burning. Make sure wick does not extend higher than 1.5" above canister.

PLACEMENT

Place the canister inside flower at top of stem.

BASE PLATE

Ensure piece is ALWAYS at or above ground level, especially pieces mounted to a concrete pad. Pad MUST be at or above ground level.

DO NOT cover base plate with more than 1" of mulch or other ground covering.

Ensure water does not pool around base of piece.

MAINTENANCE

Weld spots will turn a rust color. This is normal.

No maintenance, coatings, or other treatments are necessary.



WARNING

Keep out of reach of children. Burn torch within sight & NEVER leave unattended. Never place near anything that can catch fire.