

Mounting location for accurate measurements:

Choose a location that is not subject to direct weather elements. An ideal location is out of direct sun, on the North side of a building or in a shady spot.

Mounting instructions:

1. Remove the bracket from the thermometer and use the included screws to secure the bracket to a window frame or deck post.
2. Insert the thermometer onto the installed bracket and adjust to the desired viewing angle.