QUICK START - DIGITAL TRAVEL FLOOR DRIVE



DIGITAL TRAVEL FLOOR DRIVE













system

matrix


strip gauge

threaded connection

 Hold 2 sec to ON/OFF Press to switch PSI/BAR CR1220 battery • Max 160 PSI / 11.0 BAR • 0 shows until 5 PSI / 0.34 BAR is reached • Meas. holds for 5 secs over 10 PSI / 1.4 BAR Battery Indicator

To reset the gauge:

TURN THE PUMP ON FIRST, then press and hold the power button for 10 seconds. The gauge will turn off and on during this process, do not let go of the button until the gauge turns on again.



For more info go to: www.lezyne.com/support.php