3" Bull Bar License Plt Kit

Part No. B0007-RELOCATE

Fits: All Years - Universal License Plate Relocation Kit - Bull Bars







REMOVE CONTENTS FROM BOX. VERIFY ALL PARTS ARE PRESENT.

READ INSTRUCTIONS CAREFULLY BEFORE STARTING INSTALLATION.







10 min

Cutting Not Required

Drilling Not Required



nick @monroe truck accessories.com



1 231 903 6414



1 YEAR LIMITED WARRANTY




DO NOT OVER TORQUE. HAND TIGHTEN ONLY.



PARTS LIST:			
Qty	Part Description	Qty	Part Description
2	6-1.00mm x 20mm Screws	2	Adhesive Foam Strips

INSTALLATION PROCEDURE:

- 1. Attach two Adhesive Foam Strips on the Relocation Bracket as shown in Figure 1.
- 2. Remove center skid plate bolt from Bull Bar. Position Relocation Bracket against cross tube and on top of skid plate. Attach Relocation Bracket to bull bar using the skid plate bolt removed in this step (Figure 2). Tighten at this time



3. Attach license plate to Relocation Bracket using the included (2) 6mm x 20mm Screws. Tighten at this time

Page 1 of 2 Rev 010119

PRODUCT CARE

- Periodically check the product to ensure all fasteners are tight and components are intact.
- Regular waxing is recommended to protect the finish of the product.
- Use ONLY Non-Abrasive automotive wax. Use of any soap, polish or wax that contains an abrasive is detrimental and can scratch the finish leading to corrosion.
- Aluminum polish may be used to polish small scratches and scuffs for Stainless Steel finish.
- Mild soap may be used to clean the product for both Stainless Steel and Black finish.

FAQ's

1. Hardware's are not of correct size.

reuse the factory bolts to install the bracket.

2. Mounting Bracket are not getting Installed properly.

In some cases Illustration images shown in Installation manual may not be the exactly same as per actual vehicle images ,also if Driver / Passenger side mounting brackets are very identical in the design, suggest referring Parts Identification guide to avoid fitment issue.

3. Products are thumping / rattling after installation.

Ensure that all required mounting brackets / hardware's are installed & tighten correctly. Suggest using white lithium / regular grease between the metal to metal contact surfaces.

4. Side Bar is not aligning with vehicle / Step Pads are not aligning with vehicle doors.

Side bar may be interchanged or mounting brackets are not installed at the correct position in the vehicle. Refer Parts identification guide.

5. Missing / Excess Hardware.

Recheck hardware count as per the part list.

6. Product not installing properly.

Ensure make model year, cab length and bed size of your vehicle is listed in the application. All installation steps are followed correctly.

Page 2 of 2 Rev 010119