









UPLOADING THE MODIFIED FILE

A) Save the file received from your Manager on the Pc. Plug the device to the USB port and press the button “XTREME PERFORMANCE TOOL”.
Follow the guided procedure.



For Tuning Bundles, you can Upload more than one file by clicking on "Add New File"





WRITING OF THE MODIFIED FILE

A) Connect the OBDII/diagnostic cable to the device and to the plug of the vehicle. Select **WORK**→**WRITING** and follow the procedures on the display of the tool.

