

51 Winthrop Road Chester, Connecticut 06412-0684 Phone: (860) 526-9504 Fax: (860) 526-2009 Internet: www.whelen.com Sales/Service e-mail: aviation@,whelen.com



TSO-C30c TYPES I, II & III / TSO-C96a CLASS II APPROVED

MADE IN THE U.S.A

SPECIFICATIONS:

Nominal Operational Voltage:	28 VDC
Current Source Input Current:	
LED Forward Position Light	0.25 Amps
LED Tail Position Light	0.25 Amps
LED Anti-Collision Light (Peak@.25 Sec.)	4.0 Amps
LED Anti-Collision Light (Avg.)	0.75 Amps

EQUIPMENT LIMITATIONS:

An approved Anti-Collision / Position Light System consists of at least 2 flasher/current source units, each connected to a LED anticollision and position light lighthead.

Certain types of installations may require additional testing.

CONTINUED AIRWORTHINESS:

If any bank of LEDs fail, the lighthead module should be checked. If the module checks good, replace the flasher.

Note: To reduce eye strain, use an optical filter such as dark glasses or a blue covering dome during LED inspection.

Note: The anti-collision light will automatically shut-off after 9-10 flashes if a failure is detected.

INSTALLATION PROCEDURES:

- 1. Consider areas or locations designated by the aircraft manufacturer. Check that breakers are properly rated.
- 2. Attach the flasher using the (4) 0.156 dia. mounting holes.
- Connect the anti-collision inputs and the position light inputs according to the chart shown. Connect the cable from the lighthead to the flasher position light. Connections to be in accordance with FAA approved methods.
- 4. Check all avionic systems for interference from the installation
- 5. A flight check should be performed by a certified pilot
- 6. Update aircraft records, complete form 337 and obtain FAA field approval for installation, as necessary

Note: SYNC is a low power, bi-directional control signal. Connecting to the synchronize signal of any Whelen LED anti-collision assembly will cause the lights to flash at the same time. If synchronization is not necessary, the connection may be left open.

Installation Guide: Aviation model 7123404 P/N 01-0771234-04 Flasher/Current Source

The conditions and tests required for TSO approval of this article are minimum performance standards. It is the responsibility of those installing this article either on or within a specific type or class of aircraft to determine that the aircraft installation conditions are within the TSO standards. TSO articles must have separate approval for installation in aircraft. The article may be installed only if performed under 14 CFR part 43 or the applicable airworthiness requirements.



For warranty information regarding this product, visit www.whelen.com/warranty