


This guide shows the location of the fuse for the Supercharger Coolant Pump (V188)

This pump fuse may need to be updated to a 20A/25A fuse for CWA100/150 upgrades

B8 S4/S5 (2009-2012)

SB10 - Fuse #10 in carrier ST1 in the underhood fuse panel SB


Location: Under washer fluid filler neck



B8.5 S4/S5 (2012-2017)


SB16 - Fuse #16 in carrier ST1 in the underhood fuse panel SB

Location: Under washer fluid filler neck




C7 A6/A7 (2012-2014)

SA16 - Fuse #16 in carrier ST1 (**A**) in the underhood fuse panel SA
Location: Under washer fluid filler neck



C7.5 A6/A7 (2015-2018)

SA10 - Fuse #10 in carrier ST1 (**A**) in the underhood fuse panel SA
Location: Under washer fluid filler neck



4M Q7 (2015-2019) EA837 only

SB8 - Fuse #8 in carrier ST1 (brown) in the interior fuse panel SB

Location: Under dead pedal/footrest

