

T-MAXX 3.3

Driveshaft Assembly



Abbreviations

| | | |
|--|-----|--------------------------------|
| | CCS | Countersunk Cap Screw |
| | CS | Cap Screw |
| | FCS | Flathead Cap Screw |
| | BCS | Buttonhead Cap Screw |
| | CM | Countersunk Machine Screw |
| | RM | Roundhead Machine Screw |
| | WM | Washerhead Machine Screw |
| | SS | Shoulder Screw |
| | CST | Countersunk Self-tapping Screw |
| | RST | Roundhead Self-tapping Screw |
| | WST | Washerhead Self-tapping Screw |
| | FN | Flange Nut |
| | NL | Nylon Locknut |
| | PB | Plastic Bushing |
| | GS | Set (Grub) Screw |
| | PW | Plastic Washer |
| | AS | Aluminum Spacer |
| | PTW | PTFE Washer |
| | MW | Metal Washer |
| | E | E-Clip |
| | SW | Split Washer |
| | BB | Ball Bearing |
| | SLB | Self-lubricating Bushing |
| | NRB | Needle Roller Bearing |
| | ELW | External Lock Washer |

