



IDC5
SOFTWARE
UPDATE

TEXA

OHW 23.2.2

MARCH 2023





OHW 23.2.2

The new diagnostic features included in the **IDC5 OHW 23.2.2** update allow working on a large number of vehicles that belong to makes of the most popular manufacturers.

The work TEXA's developers carried out on agricultural vehicles, forklifts, telehandlers, construction vehicles and special vehicles guarantees all mechanics the opportunity to use diagnostic tools that are always updated and state-of-the-art, to operate successfully on most vehicles on the road.

Some of the main topics released:

New on this release:

Developed the new 3151/T83 cable for the GENIE Scissor lift Series GS model.



Developed the new 3151/T84 cable for the TOYOTA Forklift models.



OHW DIAGNOSTIC SYSTEM

27 brands updated.

(BOBCAT Engine, CUMMINS Engine, DEUTZ Engine, DEUTZ-FAHR, DOOSAN Engine, FPT Engine, GENIE, HITACHI, HURLIMANN, HYUNDAI CE, ISUZU Engine, JCB, JOHN DEERE, JOHN DEERE CE, KÄSSBOHRER GELÄNDEFahrZEUG, KRONE, KUBOTA, LAMBORGHINI, LIEBHERR, MASSEY FERGUSON, MERCEDES-BENZ Engine, SAME, STEYR, TEREX/DEMAG, TOYOTA, VOLVO CE).

DASHBOARD

4 new Dashboards (live data, adjustment, setting and scanning system).

WIRING DIAGRAMS

30 new wiring diagrams.

TECHNICAL BULLETINS

31 new technical sheets.