# Tours • LYBIH52X

# 52cm Undermount Range Hood

## Signature Features

#### **High Performance**

 Powerful air extraction of up to 600m3/h and enhanced by a 3-speed fan mode, you can boil, simmer and stir-fry.

#### **Optimal Clean Air**

 Equipped with 3-layer filters for optimal smoke and odor absorption capacity.

### **Eco Friendly LED Lights**

 Environmentally responsible LED lights (2 \* 1.5 W) provide ample clarity over the cooking area

## **Intuitive Touch Control**

• Easy to understand and easy to operate, so you can easily adjust the power and access all the important functions at your fingertips

## Easy to Clean

• Surface of the rangehood can be easily wiped down and the 3-layer aluminum micro-mesh filter can be easily handwashed to maintain its optimal performance

#### **Head-free Design**

 Sleek and head-free design gives the kitchen a modern touch and an optimal view of your cooktop



# Tours • LYBIH52X

# 52cm Undermount Range Hood

## Technical Features

Materials / Color: Stainless Steel + Galvanized body

Installation: Built-in undermount Voltage / Frequency: 220-240V, 50-60Hz

Current Amps: 1.1A
Power Cable: 1.5m

Australian Plug: 1.5r

## Range Hood Features

Power Levels:
Control Display:
Push button
Max. Air Extraction Power:
600m³ / h
Motor Power:
230W
Rated Lamp Power (each):
1.5W

LED Lights: 2
Sound Power Level: 65dB

## Filter Features

Aluminum/Stainless Steel Surface Filter: 3 layers (1 piece)

Activated Charcoal Filter: No

\*Charcoal filter is not included and can be purchased separately; size: φ175\*35mm

Duct pipe:

1.5m aluminum foil

to

75cm

# Dimensions & Weight

Packed dimensions: 580 (W) x 335 (D) x 320 (H) mm 7kg

Unpacked weight: 5.8kg

#### **EAN Number**

• 0731093140686


## Warranty

Two (2) year parts and labor

Installation Drawings

\*Extend your warranty by registering your product linarie.com.au

# 



Please refer to the user manual for detailed installation and for filter replacement instructions. Insufficient distance between the cooktop and the rangehood can result in damage to the rangehood.

Follow Us