



# Upgraded Electronic Fishing Scale

FS01

Thank you for choosing Dr.meter! Please read this manual carefully and keep it for future reference.

## Product Description

This upgraded electronic fishing scale boasts a crystal-clear LCD display and is specially designed with functions of tape, tare/zero, automatic power off, unit conversion, memory storage, summation, numeric comparison, data lock and more. It's an excellent tool for fishing, shopping, outdoor activities, and even home use!

## Specifications

**Functions:** tape, blue backlight, tare/zero, auto power off, data lock, unit conversion, memory storage, summation, numeric comparison, Overload indication and low battery indication, High precision strain gauge sensor, Stainless steel hanging bracket and concealed hook slot

**Weight range:** 0~10kg: d=5g, 10-50kg: d=10g

**Units:** kg, lb, oz

**Power:** 3V (2 x AAA battery)

**Working current:** backlight on  $\leq 10$  mA, backlight off  $\leq 5$  mA

**Operating temperature:** 10~40°C

## Package Contents

- 1 x Upgraded Electronic Fishing Scale
- 1 x User Manual
- 1 x Warranty Card

## Operation Guide

### Battery Replacement

- Open the battery cover on the back of the device
- Insert 2 AAA batteries
- Close the battery cover tightly

### Power On

- Hang the scale to keep it vertically
- Press the ON/OFF button to turn on the scale. The LCD screen will display "8888" for approximately 2 seconds.
- The scale is ready to use when the screen displays "0.0".

## How to Weigh Items

- Turn on the scale and wait until the screen displays "0.0".
- Hang the item on the scale's hook.
- Wait until the item is completely still and read the item's net weight on the LCD screen.
- After 5 seconds, the scale will lock automatically. Press the ON/OFF button to unlock the scale for your next measurement.

## Unit Conversion

Press the UNIT button to select your preferred unit (kg, lb, or oz)  
[1kg = 35oz = 2.2lb]

## Memory Storage

Press the MEMORY button to save your current measurement. The scale can hold up to 9 records.

## Summation

To add measurements together, press the MEMORY button after browsing through them. The summation will be shown after the screen displays "E".

## Numeric Comparison

When browsing the stored records, the maximum value will flash 3 times.

## Tare/Zero

To weigh items in bulk, place an empty container on the hook. Press ON/OFF to tare. Place the items in the container when the screen displays "0.0". The measurement stored on the screen is the net weight.

## Data Lock

Measurements are locked automatically after weighing. The screen will display a lock icon after approximately 2 seconds. Press the ON/OFF button to unlock the scale for your next measurement.

## Power Off

Press the ON/OFF button to turn off the scale. If the scale is locked, press the ON/OFF button once to unlock and again to turn off. The scale will power off automatically if unused for 1 minute.

## Blue Backlight

The backlight will remain on when the scale is in use. The backlight will turn off automatically if the scale is unused for 1 minute.

## Notes:

- Make sure the items to be weighed do not exceed the maximum weight.
- If the weight of the items exceeds the maximum weight range, the LCD screen will display "O-Ld". Remove the items immediately to prevent damage to the scale.

## Tape Measure

Pull out the tape from the left side of scale to measure items up to 3ft in length.

## Cautions

- Keep the scale vertical when in use.
- DO NOT use corrosive solvents to clean the scale. Use a damp cloth and mild soap to clean.
- The shell is made of ABS engineering plastic. Please wipe it with clean water or detergent via a soft cloth. Do not use corrosive substances to clean it such as benzene, nitro solvents, caustic soda solution etc.
- If the LCD screen displays "LO", replace the batteries as soon as possible.
- If the scale will not be used for an extended amount of time, remove the batteries to avoid internal leakage and corrosion.
- DO NOT repair the scale at home. Please take the device for a professional for any and all repairs.