ACCESSORY FITMENT INSTRUCTION

Product	2019 Steed 5E & MPI Nudge			
Part no.		72051T		
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Minutes	Models : Steed 5E & MPI Nudge		
(°)		Page 1 of 7		
		Date :16/09/2019		

DIAGRAM



#### Kit content:

		Qty	Description		Qty	Description
	Α	4	M10 Hex Nuts	J	2	M8 Hex Nuts
	В	6	M10 Spring Washers	K	1	Nudge Bar
	С	6	M10x30x2 Flat Washers	L	2	Top Mounting Brackets (PS and DS)
No.	D	2	M10x40x3 Flat Washers	М	1	PS Bottom Bracket
1	Е	2	M10x30 Sets	N	1	DS Bottom Bracket
T	F	2	M10x100 Bolts	0	1	Support Plate
ľ	G	2	M8x20 Sets	Р	1	U Bolt
1	Н	2	M8 Spring Washers			
п	I	4	M8x20x1.6 Flat Washers			

#### Additional equipment/Material needed for fitment :

Qty	Ratchet and Socket Set	Qty	
	Spanner Set		
	Masking Tape		

#### Precautions during fitment:

Do not cause any damage to the vehicle, apply masking tape to the front bumper to prevent damages.


Ensure that you are wearing the correct PPE clothing during Installation.

#### Directions for use:

Read all instructions carefully before installation.

Page 2 of 7

#### **Fitment Instruction:**



Page 3 of 7

## **Fitment Instruction:**


2019 Steed 5E & MI	PI Nudge	
Visual / Graphic Illustration	Step#	Description/Method
White programmers and the state of the state	3	Remove the chassis cross member. FIG 3.
FIG 3	4	With the cross member removed, place the top brackets as shown in the picture. Fit the cross member back on and tighten to specified torque. FIG 4. Use the same kit as removed from step 3.
The top brackets to be sandwiched between the chassis cross member and the mounting		Bracket with a P cut out to go on the passengers side. Bracket with a D cut out to go on the drivers side.

Page 4 of 7

## **Fitment Instruction:**

\frac{1}{2} \left( \frac{1}{2} \right) \frac{1}{2} \right( \frac{1}{2} \right) \frac{1}{2} \right) \frac{1}{2} \right( \frac{1}{2} \right) \frac{1}{2} \right) \frac{1}{2} \right( \frac{1}{2} \right) 1	Step #	Description/Method
Visual / Graphic Illustration  FIG 5  The Bottom hole goes through the chassis. The tan hole	5	On the PS, under the front bumper locate the hole in the chassis FIG 5. Fit the bracket as shown in FIG 6. Do not fully tighten.
top bolt goes above the chassis.	6	On the DS of the vehicle under the bumper locate where to mount the U Bolt FIG 7. Fit the U-bolt and bracket as shown in FIG 8
Front of vehicle		

## **Fitment Instruction:**



Step#	Description/Method
7	Replace bumper.

Page 6 of 7

## **Fitment Instruction:**

	T	
Visual / Graphic Illustration	Step #	Description/Method
G	8	Mount the nudge bar to the mounted brackets. FIG 9.
H	9	Complete
D B		
E		

#### Page 7 of 7

### Final step

Make sure bar is centralised and tighten all fasteners to specified torque. M8= 22Nm , M10= 42Nm , M6= 9Nm.

