Main features





Sectors





















The evolution of the professional shoe

- Regularly check the pattern and the thickness of the outsole. Depending on the ground and the way you walk, the shoe may lose its non-slip characteristics. Keep your shoes clean.
 Clean the shoes with cold water and soap, up to a maximum temperature of 50°C. Don't use a brush. Do not machine wash. If necessary, use a short program with cold water and do not spin.
 Possible to sterilize with chemicals and UV.
 Dry in ventilated areas and in room temperature. Don't expose the shoes to high temperatures or any heat sources since they could deform and lose its characteristics. Don't use a dryer.