

POLARIS Sportsman Ute 570 from 2017 (TBW)

Parts list for MCS 5010 TBW

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCS 10000C TBW	Computer
2	2 lengths		Velcro mounting tape 7cm long
3		<u>MCS 5014-835H</u>	<u>Control Switch assembly with OPTIONAL spray switch</u>
	1	MCS 822-90	Control Switch
	4		4 gauge x 1/2" pan head self-tap screws
	1	MCS 835H	Switch bracket with spray switch
	1	MCS 823-90	Spray switch
<u>OR</u>			
4		<u>MCS 5014-836F</u>	<u>Control Switch assembly without spray switch</u>
	1	MCS 822-90	Control Switch
	4		4 gauge x 1/2" pan head self-tap screws
	1	MCS 836H	Switch bracket without spray switch
5	1	<u>MCS 5011</u>	<u>Wiring harness</u>
a			Computer plug (26 pin)
b			Cruise Control Power Fuse (3 amp fuse)
c			Terminals for optional Spray power harness (pink & blue wires)
d			CAN-BUS Diagnostic plug connector
e			Brake switch connectors (orange & grey wires)
f			TTPS connectors (3 way plug & terminals)
fl			TTPS connector housing (3 way)
g			Control switch plugs (6 way & 3 way)
<u>OPTIONAL</u>			
6	1	<u>MCS 5010SPK</u>	<u>Spray Power Kit</u>
		MCS 5011SPH	Spray Power Harness
a			Spray control relay
b			Ground supply terminal (black wire)
c			Output power and ground wires (yellow & black wires)
d			Relay control terminals (pink & blue wires)
e			Spray power fuse (10 amp fuse)
f			Power supply terminal (red wire)
7	1	JD 046	Spray Power Plug
8	3	H 3555	Terminals for above
9	3		8g x 3/8 self-tapping screws (relay/power plug mount)
	1		M5 x 16 pan head screw (relay mount)
	1		5mm flat washer (relay mount)
	1		M5 Nyloc nut (relay mount)
10	1	JD 045M	Spray Power Socket
11	3	H 2832	Terminals for above
	1		Paper clip (terminal removal tool)
	10		150mm cable ties
	10		200mm cable ties
	10		300mm cable ties

Information, Set up and Operation Manual
Operation and User Manual
Installation Manual
Trouble shooting guide

