

YAMAHA XT1200Z Super Ténéré from 2010

Parts list for MCS 6130TBW kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCS 8000TBW C	Computer
2	2 lengths		Self-Adhesive Velcro 8cm long
		<u>MCS 4884</u>	<u>Control Switch assembly</u>
3	1	MCS 820	Control Switch
4	1	MCS 8300	Switch bracket
	4		4 gauge x 1/2" pan head self tap screw
5	1	<u>MCS 6131TBW</u>	<u>Wiring harness</u>
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor connectors (yellow wire)
d			Speed sensor connectors (blue/black wires)
e			Power & brake sensor (orange and grey wires)
f			Clutch sensor connectors (blue wire)
g			Control switch plug (6 pin)
6	1	<u>MCS 6131TPS</u>	<u>Throttle Position Sensor Wiring Harness</u>
a			Computer plug terminals
b			TPS connectors
c			TPS connector receptacle housing
	10		100mm cable ties
	10		150mm cable ties
	10		200mm cable ties
	6cm	HST3	Heat Shrink tube 3mm (speed sensor connection)
	1		Paper clip (terminal insertion tool)
	1 bottle		Throttle cable oil (Singer industrial sewing machine oil)
			Information, Set up and Operation Manual
			Operation and User Manual
			Installation Manual
			Trouble shooting guide

