

HONDA CRF1000 & CRF1000D DCT

Parts list for MCS 6380a kit (manual shift)

Parts list for MCS 6380a DCT kit (DCT shift)

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCS 8000C	Computer
2	2 lengths		Self-Adhesive Velcro 8cm long
		<u>MCS 6382</u>	<u>Electric throttle servo assembly</u>
3	1	MCS 850	Electric throttle servo
4	1	MCS 850C	Servo nose
5	3		M4 x 12 pan head screws
6	1		3/4" x 3/32" (19 x 3mm) 'O' ring
7	1	MCS 850B	Cable sealing boot
8	2	MCS 054	Wire ring cable retainer (1 spare)
9	1 length		Single sided foam tape 16cm long
10	2	HoseClamp36	Hose Clamp 46~70mm
11	1	MCSSC 580	Throttle servo cable
12	1	<u>MCS 6383</u>	<u>Wiring harness (manual shift)</u>
OR	1	<u>MCS 6383 DCT</u>	<u>Wiring harness (DCT shift)</u>
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach signal (yellow wire)
d			Speed sensor (pink wires)
e			Servo plug (4 pin)
f			Power & brake sensor plugs (orange and grey wires)
g			Ground connector (black wire)
h			Control switch plug (6 pin)
i	(only manual, not on DCT shift)		Clutch sensor (blue wire)
		<u>MCS 6384</u>	<u>Control Switch assembly</u>
13	1	MCS 820-160	Control Switch
14	1	MCS 8310	Switch bracket
	4		4 gauge x 1/2" pan head self tap screw
		<u>MCS 6385</u>	<u>Cable Interface Unit (CIU) assembly</u>
15			
16	1	MCS 6385A	CIU housing
17	1	MCS 003F	Throttle Servo spool
18	1	MCS 6386	Dual spool
19	1	MCS 003H	Bush
20	1	MCS 003K	End Cap
21	1		M5 x 45 pivot bolt
22	1	F20029	M5 guard clip
23	1		5mm plated flat washer
24	1		M4 x 10 pan head screw (servo cable retainer)
25	1	MCS 6385B	CIU mount bracket
		<u>MCS 6388</u>	<u>Carburettor cable assembly</u>
26	1	MCSCC 360	Carburettor cable
27	1	MCS003Z	6mm to 8mm adaptor washer
28	1		6mm flat washer
	10		100mm cable ties
	10		150mm cable ties

6 200mm cable ties
6 300mm cable ties

1 bottle Throttle cable oil (Singer industrial sewing machine oil)

Information, Set up and Operation Manual
Operation and User Manual
Installation Manual
Trouble shooting guide

