

SUZUKI BANDIT GSF1250S

Parts list for MCS 6700 kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCS 8000C	Computer
2	2 lengths		Velcro Mounting Tape 8cm long
		<u>MCS 6702</u>	<u>Electric Throttle Servo assembly</u>
3	1	MCS 850	Electric throttle servo
4	1	MCS 850C	Servo nose
5	3		M5 x 12 pan head screws
6	1		3/4" x 3/32" (19 x 3mm) 'O' ring
7	1	MCS 850B	Cable sealing boot
8	2	MCS 054	Wire ring cable retainer (1 spare)
9	2	MCS 6702A	Servo mounting brackets
10	1		M6 x20 bolt
11	1		6mm x 19mm flat washer
12	1	HoseClamp24	Hose Clamp 27~50mm
13	1	MCSSC 750	Throttle servo cable
14	1	<u>MCS 6711</u>	<u>Wiring harness</u>
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Tach sensor (yellow wire)
c1	1		
d			Speed sensor (co-axial wire)
d1	1	Sum MT6187-1171	One way tab housing
e			Throttle Servo plug (4 pin)
f			Power & brake sensor (orange and grey wires)
g			Ground connector (black wire)
h			Neutral sensor (blue wire)
i			Control switch plug (6 pin)
		<u>MCS 6704</u>	<u>Control Switch assembly</u>
15	1	MCS 820	Control Switch
16	1	MCS 830C	Above Bar Switch bracket
17 OR	1	MCS 831A	Below Bar Switch bracket
	4		4 gauge x 1/2" pan head self tap screw
18		<u>MCS 6705</u>	<u>Cable Interface Unit (CIU) assembly</u>
19	1	MCS 6705A	CIU housing
20	1	MCS 003F	Actuator spool
21	1	MCS 6706	Dual spool
22	1	MCS 003H	Bush
23	1	MCS 003K	End Cap
24	1		M5 x 50 pivot bolt
25	1		Pivot nut M5 Nylok nut
26	2		5mm plated flat washer
27	1		M4 x 10 pan head screw (actuator cable retainer)
28	1	MCS 6705B	CIU mounting bracket
29	1		M6 x 16 bolt
30	1		6mm flat washer
	1	<u>MCS 6708</u>	<u>Carburettor cable assembly</u>
31	1	MCSCC 360	Carburettor cable

32	1	MSC 003Z	6mm to 8mm adapter washer
33	1		6mm flat washer
34	2	MCSU 430	Throttle cable fitting tool
	10		150mm cable ties
	10		200mm cable ties
	5		300mm cable ties
	1		Throttle cable oil

Information, Set up and Operation Manual
 Operation and User Manual
 Installation Manual
 Trouble shooting guide

