


English Instructions / Manual for NÖRDIC GAME-N1022	
<p><b>Keyboard</b></p> <ul style="list-style-type: none"> <li>* Mechanical keyboard with 12 LED light modes</li> <li>* Nordic layout,105keys</li> <li>* 26 anti-ghosting keys</li> <li>* Painting laser keycaps</li> <li>* 1.50 M PVC cable</li> <li>* Material: Aluminum top cover and ABS bottom cover</li> <li>* Dimension: 444*155*38.5mm</li> <li>* Weight: 890G</li> <li>* Color: Black</li> <li>* Color: Black + Red</li> <li>* Keyboard backlight adjustment button</li> </ul> <div style="display: flex; align-items: center; margin-bottom: 10px;">  <span>, total 12 LED modes:</span> </div> <ul style="list-style-type: none"> <li>Mode 1: Snake-shaped running horse</li> <li>Mode 2: Wave</li> <li>Mode 3: Vertical, row by row</li> <li>Mode 4, Horizontal, line by line</li> <li>Mode 5, Leaning transformation</li> <li>Mode 6, Cross lighting</li> <li>Mode 7, Single Light</li> <li>Mode 8, Left and right scan</li> <li>Mode 9, Longitudinal brightening and fading</li> <li>Mode 10, Dot spread</li> <li>Mode 11,breathing</li> <li>Mode 12, Everbright.</li> </ul>	<p><b>Mouse</b></p> <p>To use the mouse please connect it to your computer's USB port (5V DC).</p> <p><b>Keys function:</b> ①Left ②Right ③ Wheel ④Froward ⑤Backward ⑥ DPI ⑦LED Control</p> <p><b>System:</b> Win 7 /Win8/Win10/Windows VISTA</p>

\* Keyboard backlight brightness adjustment:

Fn + ↑: Increase the brightness of the backlight;  
4 gears;

Fn + ↓: Decrease the brightness of the  
backlight; 4 gears;

\* Keyboard backlight running/breathing  
frequency adjustment:

Fn + ←: Decrease backlight running/breathing  
frequency; 3 gears;

Fn + →: Increase backlight running/breathing  
frequency; 3 gears;

\* Fn + Win \_ L: locks Win and APP keys and  
has a light indicating the current state;

\* Fn +[ F1 ~ F12]: Implement multimedia  
functions

FN+F1 Media

FN+F2 Volume -

FN+F2 Volume +

FN+F4 Mute

FN+F5 Stop

FN+F6 Precious track

FN+F7 Play/Pause

FN+F8 Next track

FN+F9 Mail

FN+F10 Home

FN+F11 Keyboard Lock

FN+F12 Calculator