Minn Kota News

OBSOLETE SWITCH

We have recently been informed that switch P/N 2064022 is no longer available from our supplier. This part is now listed as N/A.

We are aware there are a lot of motors still in the field that utilize this switch. It has been the entire that the P/N 2064022 switch will work in place of the P/N 2064022 switch in the Turbo series motors with the tilting handles that were in production from 1993. 1997.

To accomplish this:

- The control box that is currently on the motor would have to be reptaced with the current
- version control box, P/N 2062551.

 The P/N 2064023 switch will have to be wired differently than current models that use this I ne PAN 2004023 switch will have to be wired unterently than current moders that use the switch. Transpose the white and yellow wires that come from the speed coil in the lower unit. Do not use the blue speed coil wire. Tape the blue wire off to prevent any chance of shorting out to other wires.

Although this is not a direct substitution, it is a possible alternative for some customers with the aforementioned models.

