Vacuum Gauge Spec Sheet

— Vacuum Air Pressure Gauge -30HG to 150PSI

Measure and control the vacuum pressure of your working environment.

Our 15465 series features a 2 1/2"- wide Polycarbonate lens with easy-to-read markings, and1/4" MNPT threaded socket at the bottom for attachment. Some assembly required.

Dry or Glycerin Filled are available.

SKU	15465	15465-SS	15465-SS-OIL
SIZE NAME	Oil Filled - 1/4" NPT Brass	Dry - 1.4" NPT SS	Oil Filled - 1/4" NPT SS
Housing Material	Semisteel	Stainless Steel 316	Stainless Steel 316
Connection Material	Copper Alloy	Copper Alloy	Copper Alloy
Movement Material	Copper Alloy	Copper Alloy	Copper Alloy
Bourdon Tube Material	Copper Alloy	Copper Alloy	Copper Alloy
Window Material	Polycarbonate	Polycarbonate	Polycarbonate
Dial Size	2-1/2"	2-1/2"	2-1/2"
Thread Size	1/4" MNPT	1/4" MNPT	1/4" MNPT
Accuracy	+/- 3%	+/- 3%	+/- 3%
Scale	PSI and Bar	PSI and Bar	PSI and Bar
Range	-30 HG-150 PSI	-30 HG-150 PSI	-30 HG-150 PSI
Liquid Filling	Glycerin	No filling oil	Glycerin
Ambient Temp.	-4°F to +140°F	-4°F to +140°F	-4°F to +140°F
Working Environment	Vacuum and Pressure	Vacuum and Pressure	Vacuum and Pressure
Image	Sharing distribution on the state of the sta	BO INTERPRETATION OF THE PARTY	2 2 3 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Hardware Factory Store Inc.

1029 N Todd Ave. Azusa, CA 91702

TEL: 626.332.7744

E-MAIL: info@hfsusa.com

WEBSITE: https://hardwarefactorystore.com/

