


# Armorlite JK 2DR- Rear Seat Clearance



- Insure there is no debris in the areas between the latch and wheelhouse.
- Confirm that the insulation stops in front of the seat latch



- If the area is clear of debris and the insulator, and the rear seat still does not engage, trim back the OE carpet at the white dashed line.

