



**CHOGORI USA**

1

**Strip and prepare Cable.**

2

**Thread Seals Nut, Seals Ring, Clamp Ring and Gasket onto the cable.**

3

**Solder wire**


4

**Assemble Gasket into Clamp ring: Gasket Direction (Flat Surface to Housing)**

5

**Assemble Clamp Ring to Housing**

6

**Put Seals Ring to the end of Clamp Ring.**

7

**Assemble Seals Nut and Clamp Ring.**