

AL57 (Hilson Inverter off line) Fault Inverter HPs

AL57 is a communication fault between the Hilson inverter PCB board and Carrel control PCB board.

Ask the user to turn off the power at the HP isolator, wait 5 minutes, then power up again and put a call for heat to the HP from the system to test it.

If this does not help, next check the communication cable (as below yellow circle) to ensure there is no loose connection. If still no resolution suspect Inverter or Carrel PCB fault.

