


RW900 Wireless Aviation Headset



OPERATION

- Make sure your cell phone's Bluetooth function is turned on.
- Press the blue Pair Button for 7~8 seconds until the green LED flashes repeatedly.
- Your cell phone should display "ATC-HS" as a new device in the listing.
- Once the pairing is established, pairing is not required again.
- To turn off or conserve battery power, press the blue pairing button until the LED turns off.

ELECTRICAL SPECIFICATIONS	
RF type	Bluetooth 2.1 Class 1
Frequency	2.400 – 2.485 GHz
Max transmit	+20 dBm
RF sensitivity	90 dBm
Range	50 Ft with a line of sight (external antenna)
Battery	
Charging Voltage	5V DC only
Operation life	At least 24 hours with continuous connection after full charge
Charging time	3 ~ 5 hours