

# RJ45 Connectors with Over Molds

---

Here we have an rj45 connector with a strain relief over mold that extends around the rj45 connector. The over mold needs to be trimmed from the rj45 connector before the rjclip can be mounted.



Use a sharp utility knife to trim the molding around the rj45 connector off. Hold the end of the rj45 connector and trim away from your fingers.

The rj45 connector should look like this after trimming the over mold from the top, bottom, left, and right sides.



Attach the rjclip and ...

***Hear the click!***