

# Staging for Modular Cold Frame

R18



<u>Components for</u>		<u>Two Tier</u>	<u>Single Tier</u>
A. Corner Legs (759mm)		x 4	x 4
B. Long Sides (1170mm)		x 4	x 2
C. Cross Angles (609mm)		x 4	x 4
D. Tie Bars (280mm)		x 8	x 8
E. Anchor Bars (50mm)		x 4	x 4
F. Trays		x 4	x 2
Nuts & Bolts		x 32	x 28

1. Check all components.
2. Assemble the two end sections as shown, finger tight only, with the bolt heads to the outside of the frame.
3. Join the two end sections together using the Long Sides "B" and the remaining Tie Bars, "D".
4. Once all the components are in place, square up the framework and tighten fully. The trays can be placed in the framework either flat side up or, if being used with water matting, flat side down to form a dished tray.
5. When positioning the Cold Frame on top of the bench it may be necessary to loosen the four anchor bars to align them with the corresponding holes in the Cold Frame base rails.

