

MSDS

(Posted 10/09/2012)

The attached MSDS sheets supersede all other MSDS sheets. Please file accordingly.

VENDOR: **CARLISLE POWER TRANSMISSION A656**

STOCK# MFG# DESCRIPTION

P37-022	A22 BELT SUPRII RAWEDGE	P37-058	A58 BELT SUPRII RAWEDGE
P37-023	A23 BELT SUPRII RAWEDGE	P37-059	A59 BELT SUPRII RAWEDGE
P37-024	A24 BELT SUPRII RAWEDGE	P37-060	A60 BELT SUPRII RAWEDGE
P37-026	A26 BELT SUPRII RAWEDGE	P37-061	A61 BELT SUPRII RAWEDGE
P37-027	A27 BELT SUPRII RAWEDGE	P37-062	A62 BELT SUPRII RAWEDGE
P37-028	A28 BELT SUPRII RAWEDGE	P37-063	A63 BELT SUPRII RAWEDGE
P37-029	A29 BELT SUPRII RAWEDGE	P37-064	A64 BELT SUPRII RAWEDGE
P37-030	A30 BELT SUPRII RAWEDGE	P37-065	A65 BELT SUPRII RAWEDGE
P37-031	A31 BELT SUPRII RAWEDGE	P37-066	A66 BELT SUPRII RAWEDGE
P37-032	A32 BELT SUPRII RAWEDGE	P37-067	A67 BELT SUPRII RAWEDGE
P37-033	A33 BELT SUPRII RAWEDGE	P37-068	A68 BELT SUPRII RAWEDGE
P37-034	A34 BELT SUPRII RAWEDGE	P37-069	A69 BELT SUPRII RAWEDGE
P37-035	A35 BELT SUPRII RAWEDGE	P37-070	A70 BELT SUPRII RAWEDGE
P37-036	A36 BELT SUPRII RAWEDGE	P37-071	A71 BELT SUPRII RAWEDGE
P37-037	A37 BELT SUPRII RAWEDGE	P37-072	A72 BELT SUPRII RAWEDGE
P37-038	A38 BELT SUPRII RAWEDGE	P37-073	A73 BELT SUPRII RAWEDGE
P37-039	A39 BELT SUPRII RAWEDGE	P37-074	A74 BELT SUPRII RAWEDGE
P37-040	A40 BELT SUPRII RAWEDGE	P37-075	A75 BELT SUPRII RAWEDGE
P37-041	A41 BELT SUPRII RAWEDGE	P37-076	A76 BELT SUPRII RAWEDGE
P37-042	A42 BELT SUPRII RAWEDGE	P37-077	A77 BELT SUPRII RAWEDGE
P37-043	A43 BELT SUPRII RAWEDGE	P37-078	A78 BELT SUPRII RAWEDGE
P37-044	A44 BELT SUPRII RAWEDGE	P37-079	A79 BELT SUPRII RAWEDGE
P37-045	A45 BELT SUPRII RAWEDGE	P37-080	A80 BELT SUPRII RAWEDGE
P37-046	A46 BELT SUPRII RAWEDGE	P37-081	A81 BELT SUPRII RAWEDGE
P37-047	A47 BELT SUPRII RAWEDGE	P37-082	A82 BELT SUPRII RAWEDGE
P37-048	A48 BELT SUPRII RAWEDGE	P37-083	A83 BELT SUPRII RAWEDGE
P37-049	A49 BELT SUPRII RAWEDGE	P37-084	A84 BELT SUPRII RAWEDGE
P37-050	A50 BELT SUPRII RAWEDGE	P37-085	A85 BELT SUPRII RAWEDGE
P37-051	A51 BELT SUPRII RAWEDGE	P37-086	A86 BELT SUPRII RAWEDGE
P37-052	A52 BELT SUPRII RAWEDGE	P37-087	A87 BELT SUPRII RAWEDGE
P37-053	A53 BELT SUPRII RAWEDGE	P37-088	A88 BELT SUPRII RAWEDGE
P37-054	A54 BELT SUPRII RAWEDGE	P37-089	A89 BELT SUPRII RAWEDGE
P37-055	A55 BELT SUPRII RAWEDGE	P37-090	A90 BELT SUPRII RAWEDGE
P37-056	A56 BELT SUPRII RAWEDGE	P37-091	A91 BELT SUPRII RAWEDGE
P37-057	A57 BELT SUPRII RAWEDGE	P37-092	A92 BELT SUPRII RAWEDGE

P37-093	A93 BELT SUPRII RAWEDGE	P38-064	B64 BELT SUPRII RAWEDGE
P37-094	A94 BELT SUPRII RAWEDGE	P38-065	B65 BELT SUPRII RAWEDGE
P37-095	A95 BELT SUPRII RAWEDGE	P38-066	B66 BELT SUPRII RAWEDGE
P37-096	A96 BELT SUPRII RAWEDGE	P38-067	B67 BELT SUPRII RAWEDGE
P37-097	A97 BELT SUPRII RAWEDGE	P38-068	B68 BELT SUPRII RAWEDGE
P37-098	A98 BELT SUPRII RAWEDGE	P38-069	B69 BELT SUPRII RAWEDGE
P37-100	A100 BELT SUPRII RAWEDGE	P38-070	B70 BELT SUPRII RAWEDGE
P37-103	A103 BELT SUPRII RAWEDGE	P38-071	B71 BELT SUPRII RAWEDGE
P37-105	A105 BELT SUPRII RAWEDGE	P38-072	B72 BELT SUPRII RAWEDGE
P37-110	A110 BELT SUPRII RAWEDGE	P38-073	B73 BELT SUPRII RAWEDGE
P37-112	A112 BELT SUPRII RAWEDGE	P38-074	B74 BELT SUPRII RAWEDGE
P37-120	A120 BELT SUPRII RAWEDGE	P38-075	B75 BELT SUPRII RAWEDGE
P37-128	A128 BELT SUPRII RAWEDGE	P38-076	B76 BELT SUPRII RAWEDGE
P38-032	B32 BELT SUPRII RAWEDGE	P38-077	B77 BELT SUPRII RAWEDGE
P38-033	B33 BELT SUPRII RAWEDGE	P38-078	B78 BELT SUPRII RAWEDGE
P38-034	B34 BELT SUPRII RAWEDGE	P38-079	B79 BELT SUPRII RAWEDGE
P38-035	B35 BELT SUPRII RAWEDGE	P38-080	B80 BELT SUPRII RAWEDGE
P38-036	B36 BELT SUPRII RAWEDGE	P38-081	B81 BELT SUPRII RAWEDGE
P38-037	B37 BELT SUPRII RAWEDGE	P38-082	B82 BELT SUPRII RAWEDGE
P38-038	B38 BELT SUPRII RAWEDGE	P38-083	B83 BELT SUPRII RAWEDGE
P38-040	B40 BELT SUPRII RAWEDGE	P38-084	B84 BELT SUPRII RAWEDGE
P38-041	B41 BELT SUPRII RAWEDGE	P38-085	B85 BELT SUPRII RAWEDGE
P38-042	B42 BELT SUPRII RAWEDGE	P38-086	B86 BELT SUPRII RAWEDGE
P38-043	B43 BELT SUPRII RAWEDGE	P38-087	B87 BELT SUPRII RAWEDGE
P38-044	B44 BELT SUPRII RAWEDGE	P38-088	B88 BELT SUPRII RAWEDGE
P38-045	B45 BELT SUPRII RAWEDGE	P38-089	B89 BELT SUPRII RAWEDGE
P38-046	B46 BELT SUPRII RAWEDGE	P38-090	B90 BELT SUPRII RAWEDGE
P38-047	B47 BELT SUPRII RAWEDGE	P38-091	B91 BELT SUPRII RAWEDGE
P38-048	B48 BELT SUPRII RAWEDGE	P38-092	B92 BELT SUPRII RAWEDGE
P38-049	B49 BELT SUPRII RAWEDGE	P38-093	B93 BELT SUPRII RAWEDGE
P38-050	B50 BELT SUPRII RAWEDGE	P38-094	B94 BELT SUPRII RAWEDGE
P38-051	B51 BELT SUPRII RAWEDGE	P38-095	B95 BELT SUPRII RAWEDGE
P38-052	B52 BELT SUPRII RAWEDGE	P38-096	B96 BELT SUPRII RAWEDGE
P38-053	B53 BELT SUPRII RAWEDGE	P38-097	B97 BELT SUPRII RAWEDGE
P38-054	B54 BELT SUPRII RAWEDGE	P38-098	B98 BELT SUPRII RAWEDGE
P38-055	B55 BELT SUPRII RAWEDGE	P38-099	B99 BELT SUPRII RAWEDGE
P38-056	B56 BELT SUPRII RAWEDGE	P38-100	B100 BELT SUPRII RAWEDGE
P38-057	B57 BELT SUPRII RAWEDGE	P38-103	B103 BELT SUPRII RAWEDGE
P38-058	B58 BELT SUPRII RAWEDGE	P38-105	B105 BELT SUPRII RAWEDGE
P38-059	B59 BELT SUPRII RAWEDGE	P38-108	B108 BELT SUPRII RAWEDGE
P38-060	B60 BELT SUPRII RAWEDGE	P38-112	B112 BELT SUPRII RAWEDGE
P38-061	B61 BELT SUPRII RAWEDGE	P38-116	B116 BELT SUPRII RAWEDGE
P38-062	B62 BELT SUPRII RAWEDGE	P38-120	B120 BELT SUPRII RAWEDGE
P38-063	B63 BELT SUPRII RAWEDGE	P38-124	B124 BELT SUPRII RAWEDGE

P38-128	B128 BELT SUPRII RAWEDGE	P39-950	3VX950 BELT POWER WEDGE
P38-133	B133 BELT SUPRII RAWEDGE	P40-100	5VX1000 BELT POWER WEDGE
P38-136	B136 BELT SUPRII RAWEDGE	P40-103	5VX1030 BELT POWER WEDGE
P38-140	B140 BELT SUPRII RAWEDGE	P40-106	5VX1060 BELT POWER WEDGE
P38-144	B144 BELT SUPRII RAWEDGE	P40-108	5VX1080 BELT POWER WEDGE
P38-148	B148 BELT SUPRII RAWEDGE	P40-112	5VX1120 BELT POWER WEDGE
P38-150	B150 BELT SUPRII RAWEDGE	P40-115	5VX1150 BELT POWER WEDGE
P38-154	B154 BELT SUPRII RAWEDGE	P40-116	5VX1160 BELT POWER WEDGE
P38-158	B158 BELT SUPRII RAWEDGE	P40-118	5VX1180 BELT POWER WEDGE
P38-162	B162 BELT SUPRII RAWEDGE	P40-123	5VX1230 BELT POWER WEDGE
P38-173	B173 BELT SUPRII RAWEDGE	P40-125	5VX1250 BELT POWER WEDGE
P38-180	B180 BELT SUPRII RAWEDGE	P40-132	5VX1320 BELT POWER WEDGE
P38-195	B195 BELT SUPRII RAWEDGE	P40-140	5VX1400 BELT POWER WEDGE
P39-100	3VX1000 BELT POWER WEDGE	P40-150	5VX1500 BELT POWER WEDGE
P39-106	3VX1060 BELT POWER WEDGE	P40-160	5VX1600 BELT POWER WEDGE
P39-112	3VX1120 BELT POWER WEDGE	P40-170	5VX1700 BELT POWER WEDGE
P39-118	3VX1180 BELT POWER WEDGE	P40-180	5VX1800 BELT POWER WEDGE
P39-125	3VX1250 BELT POWER WEDGE	P40-190	5VX1900 BELT POWER WEDGE
P39-132	3VX1320 BELT POWER WEDGE	P40-200	5VX2000 BELT POWER WEDGE
P39-140	3VX1400 BELT POWER WEDGE	P40-450	5VX450 BELT POWER WEDGE
P39-150	3VX1500 BELT POWER WEDGE	P40-470	5VX470 BELT POWER WEDGE
P39-250	3VX250 BELT POWER WEDGE	P40-490	5VX490 BELT POWER WEDGE
P39-265	3VX265 BELT POWER WEDGE	P40-500	5VX500 BELT POWER WEDGE
P39-280	3VX280 BELT POWER WEDGE	P40-510	5VX510 BELT POWER WEDGE
P39-300	3VX300 BELT POWER WEDGE	P40-530	5VX530 BELT POWER WEDGE
P39-315	3VX315 BELT POWER WEDGE	P40-540	5VX540 BELT POWER WEDGE
P39-335	3VX335 BELT POWER WEDGE	P40-550	5VX550 BELT POWER WEDGE
P39-355	3VX355 BELT POWER WEDGE	P40-560	5VX560 BELT POWER WEDGE
P39-375	3VX375 BELT POWER WEDGE	P40-570	5VX570 BELT POWER WEDGE
P39-400	3VX400 BELT POWER WEDGE	P40-580	5VX580 BELT POWER WEDGE
P39-425	3VX425 BELT POWER WEDGE	P40-590	5VX590 BELT POWER WEDGE
P39-450	3VX450 BELT POWER WEDGE	P40-600	5VX600 BELT POWER WEDGE
P39-475	3VX475 BELT POWER WEDGE	P40-610	5VX610 BELT POWER WEDGE
P39-500	3VX500 BELT POWER WEDGE	P40-630	5VX630 BELT POWER WEDGE
P39-530	3VX530 BELT POWER WEDGE	P40-650	5VX650 BELT POWER WEDGE
P39-560	3VX560 BELT POWER WEDGE	P40-660	5VX660 BELT POWER WEDGE
P39-600	3VX600 BELT POWER WEDGE	P40-670	5VX670 BELT POWER WEDGE
P39-630	3VX630 BELT POWER WEDGE	P40-680	5VX680 BELT POWER WEDGE
P39-670	3VX670 BELT POWER WEDGE	P40-690	5VX690 BELT POWER WEDGE
P39-710	3VX710 BELT POWER WEDGE	P40-710	5VX710 BELT POWER WEDGE
P39-750	3VX750 BELT POWER WEDGE	P40-730	5VX730 BELT POWER WEDGE
P39-800	3VX800 BELT POWER WEDGE	P40-740	5VX740 BELT POWER WEDGE
P39-850	3VX850 BELT POWER WEDGE	P40-750	5VX750 BELT POWER WEDGE
P39-900	3VX900 BELT POWER WEDGE	P40-780	5VX780 BELT POWER WEDGE

P40-800	5VX800 BELT POWER WEDGE
P40-810	5VX810 BELT POWER WEDGE
P40-830	5VX830 BELT POWER WEDGE
P40-840	5VX840 BELT POWER WEDGE
P40-850	5VX850 BELT POWER WEDGE
P40-860	5VX860 BELT POWER WEDGE

P40-880	5VX880 BELT POWER WEDGE
P40-900	5VX900 BELT POWER WEDGE
P40-930	5VX930 BELT POWER WEDGE
P40-950	5VX950 BELT POWER WEDGE
P40-960	5VX960 BELT POWER WEDGE

MATERIAL SAFETY DATA SHEET

SECTION I: PRODUCT IDENTIFICATION

Trade Name: Rubber Power Transmission Belts

Product Class: Rubber Compounds

Hazard Ratings:

Health = 0 none -> extreme

Fire = 0 0 -> 4

Reactivity = 0

MANUFACTURER

CARLISLE POWER TRANSMISSION

2601 W. Battlefield Rd

P. O. BOX 3258

Springfield, MO 65807

Information Phone: (417) 881-7440

Emergency Phone: (417) 881-7440

Safety or Material Development Dept.

FAX Number: (417) 888-6510

Note: Transmission belts are considered to be an "article" as defined in OSHA's Hazard Communication Standard (29 CFR 1910.1200, (c), Definitions), and therefore no MSDS documentation is required. However, slippage / burning of rubber belts may release smoke or other unknown products of combustion. This Material Safety Data Sheet is intended to provide general handling guidelines and warnings which may apply to combustion products of rubber power transmission belts.

SECTION II: HAZARDOUS INGREDIENTS

There are many individual chemical components in a rubber article. These chemical components are bound or reacted in a finished or "cured" product in such a way that the end product does not display the hazardous or toxic characteristics of the component ingredients.

SECTION III: PHYSICAL DATA

Boiling Range: N/A

Vapor Pressures (mm Hg): N/A

Evaporation Rate: N/A

Appearance and Odor: Rubber or textile outer layer with characteristic rubber type odor.

Vapor Density: N/A

Solubility in Water: Insoluble

Specific Gravity: 1.12-1.42

Percent Volatile by Volume: N/A

SECTION IV: FIRE AND EXPLOSION HAZARD DATA

Flammability Classification	Auto Ignition Temperature	Extinguishing Media
OSHA DOT Flash Point: N/A	~1000° F	Foam, CO2, dry chemical, water fog

Special Fire Fighting Procedures	Unusual Fire And Explosion Hazards
Noxious gases may be formed under fire conditions. Wear NIOSH approved self-contained breathing apparatus and full protective clothing.	N/A

SECTION V: HEALTH HAZARD DATA

Threshold Limit Value	Primary Route(s) of Exposure	Effects of Overexposure
See Section II	Skin	Not known.

Medical Conditions Aggravated by Exposure	First Aid		
	Skin/Eye Contact	Inhalation	Ingestion
Possible Irritant	Skin: Wash with soap and water.	N/A	N/A

MATERIAL SAFETY DATA SHEET

SECTION VI: REACTIVITY DATA

STABILITY: ☒ Stable ☐ Unstable

HAZARDOUS POLYMERIZATION: ☒ Will not ☐ May occur

INCOMPATIBILITY - - Materials To Avoid: Strong oxidizing agents.

CONDITIONS TO AVOID: Conditions that will cause burning.

HAZARDOUS DECOMPOSITION PRODUCTS: Carbon dioxide, carbon monoxide, hydrocarbon gases.

SECTION VII: SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS SPILLED OR RELEASED:
Pick up and follow waste disposal methods.

WASTE DISPOSAL METHOD:
Dispose of in accordance with local, county, state and federal regulations.

SECTION VIII: SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION: N/A

VENTILATION: None required under normal conditions. Maintain adequate circulation to disperse concentrated fumes.

PROTECTIVE GLOVES: N/A. Recommended if irritation from handling develops.

EYE PROTECTION: None required.

OTHER PROTECTIVE EQUIPMENT: N/A

SECTION IX: SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING:
Wash before eating or smoking. Do not store near flame or ignition source.

OTHER PRECAUTIONS:
Potential for amine compounds to be nitrosated with nitrogen oxides, which produce carcinogens called N-nitroso compounds.

SECTION X: REGULATORY

REPORTABLE CHEMICAL COMPONENTS UNDER SARA 312 / 313.

Ingredients	CAS #	Weight %
Zinc Compounds	1314-13-2	0-4