

Read Before Installation



Always Ready, Always on



@CyeleeOptics

www.cyeleeoptics.com

support@cyeleeoptics.com

We strive to supply optic solutions at affordable prices. For questions or warranty support please reach via our website or above email address.



Included Items

1. *CT2 Open* Reflex Sight
2. T10 & Flathead Allen Wrenches
3. Microfiber Cloth
4. Lens Cover
5. Low Profile Optional Picatinny Mount
6. CR1632 Battery

Battery Installation

Remove the battery cap by rotating the cap in the counter-clockwise (CCW) direction. Insert the CR1632 coin cell battery negative (-) facing inward and directly in contact with the circuit. The positive (+) contact should be facing upward and visible.



Reattach the battery cap by rotating the cap in the clockwise (CW) direction until tight.

✔Note: Failure to properly tighten the battery cap could lead to intermittent LED illumination or allow moisture into the battery compartment.

Power On & Off / Brightness Control

- 1** Press the (+) button to turn the sight on. To turn the sight off press and hold the (-) button longer than 1 second and the LED dot should turn off.
- 2** Increase the brightness by pressing and (+) button. Decrease the brightness by pressing the (-) button.



③ The sight features **MOTAC(Shake Awake)** and will automatically enter standby mode after 5 minutes of non-use. As soon as the sight senses motion it will automatically become active again. (✔**Note: Shake**

Awake will not work while the optic is off)

④ The sight has 10 illumination settings; 8 daytime and 2 night vision.

Zeroing

The optic is delivered in a centered position. Normally, this means that only small adjustments are necessary, providing that the base is properly aligned.



WARNING!!! READ BEFORE USE!!!

"UP" Refers to Point of Impact NOT the actual dot! **This is an industry wide standard...**

If you rotate in the direction of the arrow that says "UP" the dot will move **DOWN**, meaning the place your bullet will hit moves UP (comparitively)

**TURN
COUNTER
CLOCKWISE**



Result



**DOT
MOVES
DOWN**



**TURN
COUNTER
CLOCKWISE**



Result




**DOT
MOVES
LEFT**



If you encounter strong resistance do NOT force the adjustment, it will cause damage not covered under our warranty!

WARNING – TEST SCREWS ON YOUR SLIDE BEFORE INSTALLING WITH OPTIC



This optic uses the RMR footprint.

☑Note: Maximum Torque is 15lb-ft, we recommend Loctite 222, anything about Blue/242 or equivalent can become permanently stuck.



Instead of a dot I see a splashed dot, half-moon shape, starburst etc

You may have astigmatism that you are not aware of. Any deformation of your red dot can be tested simply and quickly by making sure your phone camera lens is clean and then using it to look at your optic. Please check that other light sources and brightly lit objects aren't being smeared on your camera before determining if the dot is clean or smeared. If the dot is clean on your phone but distorted or smeared to your eyes this is likely due to astigmatism. Many people only realize they have it after buying red dots due to the strong pinpoint directed light which makes it obvious whether it is clear or has visual distortions. For those with astigmatism please consider trying green dots, they do not always help but many with astigmatism give feedback that they can help.

h



Warranty

3 Year Warranty Covering Manufacturing Defects - Please contact Cyelee Optics for repair or replacement.

This warranty does not cover normal wear and tear, modifications, misuse, accidents.



CYELEE

Cyelee Optics

cyeleeoptics.com